HIGHWAYS REPORT. North Cadbury

Parish Hill - Halfway up the hill there is an artificially created pothole ,where the newly laid surface surrounding the drain cover is deep enough to create a substantial drop .I have reported this as a pothole ,interestingly the council had "white lined "around it within 24 hours and advised me of their intentions carry out remedial work. It begs the question of how and who signed off the resurfacing work on Cary Road.

High Street - On the inside edge of the bend the strip repair is generally poor and there are 3 potholes developing.

Woolston Rd - Opposite the PC sign one of the kerb stones has been pushed over

Further up the road ,near the speed restriction sign there are 2 potholes next to the manhole cover.

Dodinall House Rd - Pothole on left hand side near the new houses Further up the road ,20 metres in front of the field gate there is a hole developing in front of a previous strip edge repair , you could argue that the previous repair has not been tapered into the road and this shoulder that is created there is hit by the vehicle tyres and digs up the surface.

Corkscrew Lane - First bend next to the Farm at the Sandbrook end there are several holes ,some penetrating to the large stone substrate.

Stoke Lane -Outside new Black houses a hole ,almost certainly due to the construction traffic .

West street - Again a hole exposing the larger substrate Rocks ,on the straight approaching Yarlington /Stags .

This report covers what I consider new problems ,there are previously reported items still outstanding and I am sure there will soon be new items to report. It is noticeable that some of these issues are either in previously repaired areas or adjacent to them.

All these issues have been logged with Somerset Council ,who seem to be quite active in repairs , we shall see how that goes as the budget tightens .

Chris Jose